



| STOCK CODE | DESCRIPTION                                       | MAN.PART NUMBER | DRAWING REF |
|------------|---|-----------------|-------------|
| XSMS0002   | SLUSH MACHINE SUMMIT - SUPPORTING FRAME FOOT      | 02.AA0024.001   | 2           |
| XSMS0006   | SLUSH MACHINE SUMMIT - FAIRLEAD                   | 04.ZZ0007.001   | 6           |
| XSMS0007   | SLUSH MACHINE SUMMIT - POWER CABLE                | 04.ZZ0012.001   | 7           |
| XSMS0010   | SLUSH MACHINE SUMMIT - MAIN SWITCH                | 04.AA0036.001   | 10          |
| XSMS0012   | SLUSH MACHINE SUMMIT - FUNCTION SWITCH            | 04.BA0018.001   | 12          |
| XSMS0015   | SLUSH MACHINE SUMMIT - EVAPORATOR SUPPORT         | 02.BA0013.002   | 15          |
| XSMS0017   | SLUSH MACHINE SUMMIT - EVAPORATOR BEARING LID     | 02.BA0014.001   | 17          |
| XSMS0019   | SLUSH MACHINE SUMMIT - SAFETY TUBE                | 02.BA0047.001   | 19          |
| XSMS0020   | SLUSH MACHINE SUMMIT - SAFETY BAR                 | 05.BA0002.001   | 20          |
| XSMS0024   | SLUSH MACHINE SUMMIT - LID SWITCH                 | 04.BA0024.001   | 24          |
| XSMS0027   | SLUSH MACHINE SUMMIT - LID GRATING                | 02.BA0231.001   | 27          |
| XSMS0028   | SLUSH MACHINE SUMMIT - LID                        | 02.BA0006.001   | 28          |
| XSMS0030   | SLUSH MACHINE SUMMIT - UNDER-LID                  | 02.BA0005.001   | 30          |
| XSMS0031   | SLUSH MACHINE SUMMIT - BOWL 12LT                  | 02.BA0021.001   | 31          |
| XSMS0032   | SLUSH MACHINE SUMMIT - BOWL GASKET                | 02.BA0009.001   | 32          |
| XSMS0035   | SLUSH MACHINE SUMMIT - FIXING KNOB                | 04.BA0022.001   | 35          |
| XSMS0036   | SLUSH MACHINE SUMMIT - DRIP PAN GRATING           | 02.BA0033.001   | 36          |
| XSMS0037   | SLUSH MACHINE SUMMIT - DRIP PAN                   | 02.BA0032.001   | 37          |
| XSMS0859   | SLUSH MACHINE SUMMIT - VITREX PIPE                | 04.ZZ0065.001   | 38          |
| XSMS0044   | SLUSH MACHINE SUMMIT - SAFETY MICROSWITCH         | 04.BA0070.001   | 44          |
| XSMS0050   | SLUSH MACHINE SUMMIT - FUSE HOLDER                | 04.BA0013.001   | 50          |
| XSMS0058   | SLUSH MACHINE SUMMIT - HANDLE TAP                 | 02.BA0003.001   | 58          |
| XSMS0060   | SLUSH MACHINE SUMMIT - TAP LEVER SUPPORT          | 02.BA0002.001   | 60          |
| XSMS0061   | SLUSH MACHINE SUMMIT - TAP SPRING                 | 04.BA0021.001   | 61          |
| XSMS0063   | SLUSH MACHINE SUMMIT - O-RING TAP                 | 04.BA0026.001   | 63          |
| XSMS0074   | SLUSH MACHINE SUMMIT - THERMOSTAT                 | 04.BA0031.001   | 74          |
| XSMS0075   | SLUSH MACHINE SUMMIT - GEARED MOTOR               | 04.BA0003.001   | 75          |
| XSMS0076   | SLUSH MACHINE SUMMIT - SLUSH CONSISTENCY SPRING   | 04.BA0025.001   | 76          |
| XSMS0077   | SLUSH MACHINE SUMMIT - CONSISTENCY SPRING SUPPORT | 02.BA0040.001   | 77          |
| XSMS0078   | SLUSH MACHINE SUMMIT - NUT                        | ZZ.DA0004.001   | 78          |
| XSMS0079   | SLUSH MACHINE SUMMIT - ADJUSTMENT SCREW           | 02.BA0039.001   | 79          |
| XSMS0080   | SLUSH MACHINE SUMMIT - CONSISTENCY MICRO          | 04.BA0004.001   | 80          |
| XSMS0081   | SLUSH MACHINE SUMMIT - SCREW                      | ZZ.VI0032.001   | 81          |
| XSMS0082   | SLUSH MACHINE SUMMIT - NUT                        | ZZ.DA0008.001   | 82          |
| XSMS0091   | SLUSH MACHINE SUMMIT - UPPER MIXING UNIT          | 02.BA0049.002   | 91          |
| XSMS0094   | SLUSH MACHINE SUMMIT - SPIRAL ATTACHMENT KNOB     | 02.BA0034.001   | 94          |
| XSMS0102   | SLUSH MACHINE SUMMIT - O-RING                     | 04.BA0030.001   | 102         |
| XSMS0103   | SLUSH MACHINE SUMMIT - SCRAPING WASHER            | ZZ.RO0018.001   | 103         |
| XSMS0106   | SLUSH MACHINE SUMMIT - BOILER / FILTER            | 02.BA0203.002   | 106         |
| XSMS0108   | SLUSH MACHINE SUMMIT - COMPRESSOR                 | 04.BA0034.001   | 108         |
| XSMS0109   | SLUSH MACHINE SUMMIT - COMPR ELEC PARTS KIT       | 05.ZZ0029.002   | 109         |
| XSMS0110   | SLUSH MACHINE SUMMIT - VENTILATOR MOTOR           | 04.BB0002.001   | 110         |
| XSMS0111   | SLUSH MACHINE SUMMIT - FAN                        | 04.BB0003.001   | 111         |
| XSMS0112   | SLUSH MACHINE SUMMIT - TIMER 2                    | 04.BB0013.001   | 112         |
| XSMS0115   | SLUSH MACHINE SUMMIT - GEAR MOTOR FAN             | 05.BA0012.002   | 115         |
| XSMS0125   | SLUSH MACHINE SUMMIT - LID ELECTRICAL PLUG        | 04.BA0039.001   | 125         |
| XSMS0287   | SLUSH MACHINE SUMMIT - CONTROL PANEL              | 02.BB0060.001   | 287         |
| XSMS0288   | SLUSH MACHINE SUMMIT - CONTROL HATCH              | 02.BB0061.001   | 288         |
| XSMS0008   | SLUSH MACHINE SUMMIT - GLOBE                      | 04.BB0027.001   | 365         |
| XSMS0390   | SLUSH MACHINE SUMMIT - FUSE                       | 04.AB0039.001   | 390         |
| XSMS0392   | SLUSH MACHINE SUMMIT - FUSE HOLDER                | 04.AB0038.001   | 392         |
| XSMS0401   | SLUSH MACHINE SUMMIT - CONVEYOR                   | 02.BB0099.001   | 401         |
| XSMS0402   | SLUSH MACHINE SUMMIT - CONDENSER                  | 04.BB0067.001   | 402         |
| XSMS0728   | SLUSH MACHINE SUMMIT - BRONZE FERRULE             | 02.BA0257.001   | 728         |
| XSMS0810   | SLUSH MACHINE SUMMIT - SUCTION GASKET             | 02.BA0025.001   | 810         |
| XSMS0858   | SLUSH MACHINE SUMMIT - COMP SPIRAL DRIVE          | 05.BA0016.002   | 858         |